

JUN 13 2016

RECEIVED

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

BRADENHEAD TEST REPORT

Operator Name APACHE CORP	API Number 30 025 06535
Property Name EBDU	Well No. 27

Surface Location								
UL-Lot E	Section 11	Township 21S	Range 37E	Feet from 2310	N/S Line FWL	Feet From 330	E/W Line FWL	County LEA


Well Status

TA'D WELL ☒ YES	☐ NO	SHUT-IN ☒ YES	☐ NO	INJECTOR ☒ IN	SWD	PRODUCER ☐ OIL	☐ GAS	DATE 4-14-16
--	-----------------------------	--	-----------------------------	--	-----	--	------------------------------	------------------------

OBSERVED DATA

	(A)Surface	(B)Interm(1)	(C)Interm(2)	(D)Prod Csg	(E)Tubing
Pressure	☒	☒		☒	☒
Flow Characteristics					
Puff	☒ Y / ☐ N	☒ Y / ☐ N	☐ Y / ☐ N	☒ Y / ☐ N	CO2 ☐
Steady flow	☐ Y / ☒ N	☐ Y / ☒ N	☐ Y / ☐ N	☐ Y / ☒ N	WTR ☐
Surges	☐ Y / ☒ N	☐ Y / ☒ N	☐ Y / ☐ N	☐ Y / ☒ N	GAS ☐
Down to nothing	☒ Y / ☐ N	☒ Y / ☐ N	☐ Y / ☐ N	☒ Y / ☐ N	Type of Fluid
Gas or Oil	☐ Y / ☒ N	☐ Y / ☒ N	☐ Y / ☐ N	☐ Y / ☒ N	Injected for
Water	☐ Y / ☒ N	☐ Y / ☒ N	☐ Y / ☐ N	☐ Y / ☒ N	Waterflood if
					applies.

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

Signature: 	OIL CONSERVATION DIVISION
Printed name: DAVID CUMMINGS	Entered into RBDMS
Title: SR PUMPER	Re-test
E-mail Address:	
Date: 4-14-16	Phone:
Witness: David Healy	