

JUN 13 2016

4

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

RECEIVED

BRADENHEAD TEST REPORT

Operator Name APACHE CORP	API Number 3002506538
Property Name EBDO	Well No. 28

Surface Location									
UL - Lot 7	Section 12	Township 21S	Range 37E	Feet from 330	N/S Line ENL	Feet From 460	E/W Line FWL	County LEA	

Well Status

TA'D WELL ☒ YES ☐ NO	SHUT-IN ☐ YES ☒ NO	INJECTOR ☒ INJ ☐ SWD	PRODUCER ☐ OIL ☐ GAS	DATE 4.14.16
--	--	--	---	------------------------

OBSERVED DATA

	(A)Surface	(B)Interm(1)	(C)Interm(2)	(D)Prod Csg	(E)Tubing
Pressure	0	0		0	1525
Flow Characteristics					
Puff	Y/N	Y/N	Y/N	Y/N	CO2 ☐
Steady Flow	Y/N	Y/N	Y/N	Y/N	WTR ☐
Surges	Y/N	Y/N	Y/N	Y/N	GAS ☐
Down to nothing	Y/N	Y/N	Y/N	Y/N	Type of Fluid Injected for Waterflood if applies
Gas or Oil	Y/N	Y/N	Y/N	Y/N	
Water	Y/N	Y/N	Y/N	Y/N	

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

David Cummings

Signature: <i>David Cummings</i>	OIL CONSERVATION DIVISION
Printed name: DAVID CUMMINGS	Entered into RBDMS
Title: SR PUMPER	Re-test
E-mail Address:	
Date: 4.14.16	
Phone:	
Witness: <i>Kristen Hardy</i>	