

JUN 13 2016

4

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

RECEIVED

BRADENHEAD TEST REPORT

Operator Name APACHE CORP		API Number 30 025 06556	
Property Name EBDU		Well No. 37	

Surface Location									
UL Lot E	Section 13	Township 21S	Range R37E	Feet from 1900	N/S Line FWL	Feet From 660	E/W Line FWL	County LEA	

Well Status


TA'D WELL ☒ YES ☐ NO	SHUT-IN ☐ YES ☒ NO	INJECTOR ☒ INJ ☐ SWD	PRODUCER ☐ OIL ☐ GAS	DATE 4-27-16
--	--	--	---	------------------------

OBSERVED DATA

	(A)Surface	(B)Interm(1)	(C)Interm(2)	(D)Prod Csg	(E)Tubing
Pressure	0	0		A	1250
Flow Characteristics					
Puff	☒ Y / ☐ N	☒ Y / ☐ N	☐ Y / ☐ N	☒ Y / ☐ N	CO2
Steady Flow	☐ Y / ☒ N	☐ Y / ☒ N	☐ Y / ☐ N	☐ Y / ☒ N	WTR
Surge	☐ Y / ☒ N	☐ Y / ☒ N	☐ Y / ☐ N	☒ Y / ☐ N	GAS
Down to nothing	☒ Y / ☐ N	☒ Y / ☐ N	☐ Y / ☐ N	☐ Y / ☒ N	Type of Fluid
Gas or Oil	☐ Y / ☒ N	☐ Y / ☒ N	☐ Y / ☐ N	☐ Y / ☒ N	Injected for
Water	☐ Y / ☒ N	☐ Y / ☒ N	☐ Y / ☐ N	☐ Y / ☒ N	Waterflood if applies

Remarks Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

In Shop

Signature: 		OIL CONSERVATION DIVISION	
Printed name: DAVID CUMMINGS		Entered into RBDMS	
Title: SR DUMPER		Re-test	
E-mail Address:			
Date:	Phone:		
	Witness:		