OCD-HOBBS

Form 3160-5 (March 2012)

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

FORM APPROVED OMB No. 1004-0137 Expires: October 31, 2014

5. Lease Serial No. NMNM56265

SUNDRY NOTICES AND REPORTS ON WELLS

	roposals to drill or to re-enter an 3160-3 (APD) for such proposals.	6. II Indian, Atlottee or Tribe Name	
SUBMIT IN TRIPLIC	7. If Unit of CA/Agreement, Name and/or No.		
1. Type of Well	,		
Oil Well Gas Well	8. Well Name and No. Federal L #1 SWD		
2. Name of Operator FDW LLC (OGRID #148530) Contact: TIM	GREEN - Email: tgreen@nearburg.com	9. API Well No 30-025-20811	
3a. Address 3b. Phone No. (include area code) 3b. Phone No. (include area code) 432-818-2940		10. Field and Pool or Exploratory Area YATES-SEVEN RIVERS (SWD)	
4. Location of Well (Footage, Sec., T., R., M., or Surve	ey Description)	11. County or Parish, State	
Sec 25, T20S R34E, NMPM, SENW 1650FNL 1980FWL		LEA COUNTY, NEW MEXICO	
12. CHECK THE APPR	COPRIATE BOX(ES) TO INDICATE NATURE OF N	NOTICE, REPORT OR OTHER DATA	
TYPE OF SUBMISSION	TYPE OF ACTION		
Notice of Intent Acidiz	Casing Fracture Treat	Production (Start/Resume) Water Shut-Off Reclamation Well Integrity	
Subsequent Report	Repair New Construction	Recomplete	
	e Plans	Temporarily Abandon	
Final Abandonment Notice Conve	ert to Injection Plug Back	Water Disposal	
the proposal is to deepen directionally or recomp Attach the Bond under which the work will be pe following completion of the involved operations.	lete horizontally, give subsurface locations and measurformed or provide the Bond No. on file with BLM/B If the operation results in a multiple completion or re Notices must be filed only after all requirements, incl	ing date of any proposed work and approximate duration thereof. I used and true vertical depths of all pertinent markers and zones. BIA. Required subsequent reports must be filed within 30 days ecompletion in a new interval, a Form 3160-4 must be filed once uding reclamation, have been completed and the operator has	
Please see attached regarding operations between	een April 4, 2016 and April 17, 2016.		
Repair Well. Had hole in tubing. Replace one (1 See attached morning reports for detail.) joint of tubing. Tested casing to 500#. Pat Mcl	Kelvy with BLM witnessed and approved test.	
	HOBBS OCD		
	MAY 1 9 2016		
	RECEIVED	SUBJECT TO LIKE APPROVAL BY STATE	
I hereby certify that the foregoing is true and correct. TIM GREEN	Name (Printed/Typed)		

14. I hereby certify that the foregoing is true and correct. Name (Printed/Typed) TIM GREEN Tit	le PRODUCTION N	MANAGER
Signature In- Bandon Da	te 04/20/2016	ACCEPTED FOR RECORD
THIS SPACE FOR FEDERA	L OR STATE O	FF CE USE
Approved by	Title	MAY 5 2015
Conditions of approval, if any, are attached. Approval of this notice does not warrant or certificate that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.	PR Swary	
Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person fictitious or fraudulent statements or representations as to any matter within its jurisdiction.	knowingly and willfull	y to make to any department or agency of the United States any false
(Instructions on page 2)		

Accepted for Record Only

WAS JOCK 6/15/2016

TIGHT HOLE-PLEASE DO NOT RELEASE ANY INFORMATION ON THIS WELL

Federal L Com #1
Morrow
Lea County, New Mexico
** ALL COSTS ARE FIELD ESTIMATES **

- 4/5/2016 Road rig and crew to location from Ross Ranch 22 #7. MIRU Lucky Services pulling unit.

 ND wellhead & NU BOP. Release On/Off tool from pkr. Put valve on tubing. Close BOP rams. SDFN. Will POOH w/ tbg & On/Off tool in the morning before hydrotesting tbg back in w/ redressed On/Off tool.
- 4/6/2016 Remove valve from tubing. Open BOP rams. POOH w/ 111 jts- 2 7/8" L-80 6.5# EUE 8rd (TK-70 internally coated) tubing, 2 7/8" T2 On/Off retrieving head. Redress On/Off head putting new seals inside. MIRU Hydrostatic Tubing testers to test 2 7/8" tbg to 6000# above slips while RIH. RIH w/ 2 7/8" T2 On/Off retrieving head, 81 jts- 2 7/8" L-80 6.5# EUE 8rd (TK-70 internally coated) tubing where we found 82nd jt (30 jts from surface) while hole in it. Pull hydrotesters tools and LD bad jt. Continue to hydrotest 2 7/8" L-80 tbg. RIH w/ 30 jts- 2 7/8" L-80 tbg (internally coated) for a total of 111 jts. PU new jt to replace bad jt on top (landing jt). Left On/Off just off of pkr not latching to pump pkr fluid. Had TRM pump truck hook up to csg and pump 110 Bbls 2% KCL w/ double inhibited pkr fluid @ 1.5 bpm. Latch On/Off to pkr. Had TRM pump truck test csg to 500# and hold for 10 minutes. Held good pressure. Bled off pressure. ND BOP & NU wellhead. Had 6000# tension when landing tubing flange. RDMO TRM pump truck & Lucky Services pulling unit. SDFN. Will have TRM pump truck do official MIT w/ OCD & BLM in the morning to put well back on injection.
- 4/7/2016 RU TRM pump truck to csg w/ 1000# chart recorder to perform MIT for BLM and OCD.

 Pressured csg to 500#. Set chart recorder on 60 minutes (electronic timer). Kept pressure on csg for 30 minutes with chart recording the pressure. Finish pressure was 500#. Held good pressure w/ no pressure loss. Had Pat McKelvey w/ BLM witness and approve MIT test. The OCD came to location and also approved chart, but did not witness test. RDMO TRM pump truck and chart recorder. Opened well to start injection. Will send chart in to Midland office to be filled with subsequent report. FINAL REPORT.

HOBBS OCD

MAY 1 9 2016

RECEIVED

