

JUN 13 2016

RECEIVED

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

BRADENHEAD TEST REPORT

Operator Name XTO Energy, Inc	API Number 30-025-28924
Property Name Seven Rivers Queen Waterflood, North	Well No. 11

7. Surface Location

UL - Lot G	Section 4	Township 22S	Range 36E	Feet from 2623	N/S Line North	Feet From 2636	E/W Line East	County Lea
---------------	--------------	-----------------	--------------	-------------------	-------------------	-------------------	------------------	---------------

Well Status

TA'D WELL YES	NO	YES	SHUT-IN NO	INJECTOR INJ	SWD	PRODUCER OIL	GAS	DATE 5-16-2016
------------------	----	-----	---------------	-----------------	-----	-----------------	-----	-------------------

OBSERVED DATA

	(A) Surface	(B) Interm(1)	(C) Interm(2)	(D) Prod Csng	(E) Tubing
Pressure	Ø	Ø		Ø	3
Flow Characteristics					
Puff	Y / (N)	Y / (N)	Y / N	Y / (N)	CO2
Steady Flow	Y / (N)	Y / (N)	Y / N	Y / (N)	WTR ✓
Surges	Y / (N)	Y / (N)	Y / N	Y / (N)	GAS
Down to nothing	(Y) / N	(Y) / N	Y / N	(Y) / N	Type of Fluid Injected for Waterflood if applies.
Gas or Oil	Y / (N)	Y / (N)	Y / N	Y / (N)	
Water	Y / (N)	Y / (N)	Y / N	Y / (N)	

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

Signature: <i>Alan Miller-XTO Energy</i>	OIL CONSERVATION DIVISION
Printed name:	Entered into RBDMS
Title:	Re-test
E-mail Address:	
Date: 5-16-2016	
Phone: 575-441-1641	
Witness:	