

JUN 14 2016

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

RECEIVED

BRADENHEAD TEST REPORT

Operator Name Apache Corp.				API Number 30-025-05793				
Property Name NMGSAU				Well No. 103 13				
Surface Location								
UL - Lot M	Section 32	Township 19S	Range 37E	Feet from 660	N/S Line S	Feet From 660	E/W Line W	County Lea

Well Status

YES	TA'D WELL	NO	YES	SHUT-IN	NO	INJ	INJECTOR	SWD	OIL	PRODUCER	GAS	DATE 6-8-13
-----	-----------	----	-----	---------	----	------------	----------	-----	-----	----------	-----	-----------------------

OBSERVED DATA

	(A)Surface	(B)Interm(1)	(C)Interm(2)	(D)Prod Csg	(E)Tubing
Pressure	0	40		50	1070
Flow Characteristics					
Puff	Y/N	Y/N	Y/N	Y/N	CO2 —
Steady Flow	Y/N	Y/N	Y/N	Y/N	WTR ☒
Surges	Y/N	Y/N	Y/N	Y/N	GAS —
Down to nothing	Y/N	Y/N	Y/N	Y/N	Type of Fluid
Gas or Oil	Y/N	Y/N	Y/N	Y/N	Injected for
Water	Y/N	Y/N	Y/N	Y/N	Waterflood if
					applies.

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

Signature: J.D. Ellison		OIL CONSERVATION DIVISION	
Printed name: Jim Ellison		Entered into RBDMS	
Title: Instrument Tech		Re-test	
E-mail Address: J.D.Ellison @ apache corp. com			
Date:	Phone: 575-441-7734		
Witness:			