

HOBBS OCD

JUN 27 2016

RECEIVED

District I
1625 N French Dr., Hobbs, NM 88240
Phone: (575) 393-6161 Fax: (575) 393-0720

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

BRADENHEAD TEST REPORT

Operator Name Chevron USA Inc.	API Number 30-025-12286
Property Name WEST DOLLARHIDE DRINKARD UNIT	Well No. 64

7. Surface Location									
UL - Lot I	Section 31	Township 24S	Range 38E		Foot from 998	N/S Line S	Foot From 660	E/W Line E	County LEA

Well Status

Well Status A	SHUT-IN NO	PRODUCING INJ	DATE 05-26-16
------------------	---------------	------------------	------------------

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

OBSERVED DATA

If bradenhead flowed water, check all of the descriptions that apply:

	(A)Surf-Intern	(B)Interm(1)-Interm(2)	(C)Interm-Prod	(D)Prod Casing	(E)Tubing
Pressure	Ø	Ø	N/A	Ø	1425 PSI
Flow Characteristics					
Puff	Y/N	Y/N	Y/N	Y/N	
Steady Flow	Y/N	Y/N	Y/N	Y/N	
Surges	Y/N	Y/N	Y/N	Y/N	
Down to nothing	Y/N	Y/N	Y/N	Y/N	
Gas or Oil	Y/N	Y/N	Y/N	Y/N	
Water	Y/N	Y/N	Y/N	Y/N	


If bradenhead flowed water, check all of the descriptions that apply:

CLEAR	FRESH	SALTY	SULFUR	BLACK
-------	-------	-------	--------	-------

Remarks:

INJECTING AT THIS TIME ☒ WTR, ☐ GAS, ☐ CO2

No Wizzness When Test Was done.

Signature: 	OIL CONSERVATION DIVISION
Printed name: DALTON PINKSTON	Entered into RBDMS
Title: FSA	Re-test 
E-mail Address: DPIN@CHEVRON.COM	
Date: 05-26-2016	
Phone: 432-208-1086	
Witness:	