

JUN 27 2016

RECEIVED

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

BRADENHEAD TEST REPORT

Operator Name Chevron USA Inc.	API Number 30-025-31488
Property Name WEST DOLLARHIDE DRINKARD UNIT	Well No. 121

7. Surface Location

UL - Lot E	Section 32	Township 24S	Range 38E	Feet from 2176	N/S Line N	Feet From 656	E/W Line W	County LEA
---------------	---------------	-----------------	--------------	-------------------	---------------	------------------	---------------	---------------

Well Status

Well Status A	SHUT-IN NO	PRODUCING INJ	DATE 05-26-16
------------------	---------------	------------------	------------------

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

OBSERVED DATA

If bradenhead flowed water, check all of the descriptions that apply:

	(A)Surf-Interm	(B)Interm(1)-Interm(2)	(C)Interm-Prod	(D)Prod Casing	(E)Tubing
Pressure	φ	φ	N/A	φ	1450 PSI
Flow Characteristics					
Puff	Y / (N)	Y / (N)	Y / N	Y / (N)	
Steady Flow	Y / (N)	Y / (N)	Y / N	Y / (N)	
Surges	Y / (N)	Y / (N)	Y / N	Y / (N)	
Down to nothing	(Y) / N	(Y) / N	Y / N	(Y) / N	
Gas or Oil	Y / (N)	Y / (N)	Y / N	Y / (N)	
Water	Y / (N)	Y / (N)	Y / N	Y / (N)	

If bradenhead flowed water, check all of the descriptions that apply:

CLEAR	FRESH	SALTY	SULFUR	BLACK
-------	-------	-------	--------	-------

Remarks:

INJECTING AT THIS TIME ☒ WTR, ☐ GAS, ☐ CO2

No Witness when test was done.

Signature: <i>Dalton Pinkston</i>	OIL CONSERVATION DIVISION
Printed name: DALTON PINKSTON	Entered into RBDMS
Title: FSA	Re-test
E-mail Address: DPIN@CHEVRON.COM	
Date: 05-26-16	Phone: 432-208-1086
Witness:	