

JUN 30 2016

RECEIVED

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

BRADENHEAD TEST REPORT

Operator Name Apache Corp		API Number 30-025-3882X	
Property Name Rugere Wood		Well No. 11 ✓	

7. Surface Location

UL - Lot G	Section 22	Township 22S	Range 37E	Feet from 2160	N/S Line N	Feet From 1765	E/W Line E	County Lea
----------------------	----------------------	------------------------	---------------------	--------------------------	----------------------	--------------------------	----------------------	----------------------

Well Status

TA'D WELL ☒ YES	☒ NO	SHUT-IN ☒ YES	☒ NO	INJ	INJECTOR	SWD	☒ OIL	PRODUCER	GAS	DATE 5/25/16
--	--	--	--	-----	----------	-----	---	----------	-----	------------------------

OBSERVED DATA

	(A) Surface	(B) Interm(1)	(C) Interm(2)	(D) Prod Casing	(E) Tubing
Pressure	Φ	NA	NA	30	100
Flow Characteristics					
Puff	Y/N	Y/N	Y/N	Y/N	CO2 —
Steady Flow	Y/N	Y/N	Y/N	Y/N	WTR —
Surges	Y/N	Y/N	Y/N	Y/N	GAS —
Down to nothing	Y/N	Y/N	Y/N	Y/N	Type of Fluid
Gas or Oil	Y/N	Y/N	Y/N	Y/N	Injected for
Water	Y/N	Y/N	Y/N	Y/N	Waterflood if
					applies

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

Signature: Jerad Gladden		OIL CONSERVATION DIVISION	
Printed name: Jerad Gladden		Entered into RBDMS	
Title: Mechanic II		Re-test	
E-mail Address: Jerad.Gladden@apachecorp.com			
Date: 5/25/16	Phone: 575 390-3913		
Witness: [Signature]			