

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

OCD Artesia

FORM APPROVED
OMB NO. 1004-0135
Expires: July 31, 2010

SUNDRY NOTICES AND REPORTS ON WELLS
Do not use this form for proposals to drill or to re-enter an abandoned well. Use form 3160-3 (APD) for such proposals.

5. Lease Serial No.
NMNM67986

6. If Indian, Allottee or Tribe Name

7. If Unit or CA/Agreement, Name and/or No.

8. Well Name and No.
XION FEDERAL 02

9. API Well No.
30-025-31793-00-S1

10. Field and Pool, or Exploratory
YOUNG

11. County or Parish, and State
LEA COUNTY, NM

SUBMIT IN TRIPLICATE - Other instructions on reverse side.

1. Type of Well
 Oil Well Gas Well Other

2. Name of Operator
CHEVRON USA INCORPORATED Contact: CINDY H MURILLO
E-Mail: CHERRERAMURILLO@CHEVRON.COM

3a. Address
15 SMITH ROAD
MIDLAND, TX 79705

3b. Phone No. (include area code)
Ph: 575-263-0431
Fx: 575-263-0445

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)
Sec 18 T18S R32E SENE 2310FNL 330FEL

12. CHECK APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION	TYPE OF ACTION			
<input checked="" type="checkbox"/> Notice of Intent	<input type="checkbox"/> Acidize	<input type="checkbox"/> Deepen	<input type="checkbox"/> Production (Start/Resume)	<input type="checkbox"/> Water Shut-Off
<input type="checkbox"/> Subsequent Report	<input type="checkbox"/> Alter Casing	<input type="checkbox"/> Fracture Treat	<input checked="" type="checkbox"/> Reclamation	<input type="checkbox"/> Well Integrity
<input type="checkbox"/> Final Abandonment Notice	<input type="checkbox"/> Casing Repair	<input type="checkbox"/> New Construction	<input type="checkbox"/> Recomplete	<input type="checkbox"/> Other
	<input type="checkbox"/> Change Plans	<input type="checkbox"/> Plug and Abandon	<input type="checkbox"/> Temporarily Abandon	
	<input type="checkbox"/> Convert to Injection	<input type="checkbox"/> Plug Back	<input type="checkbox"/> Water Disposal	

13. Describe Proposed or Completed Operation (clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recompleat horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompleat in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection.)

CHEVRON IS SUBMITTING PROPOSED PLANS FOR CLEANING UP THE ABOVE SUBJECT WELL. PLEASE FIND ATTACHED PHOTO'S AND RELAVANT INFORMATION.
*** PLEASE FORWARD TO JIM AMOS***

HOBBS OCD

JUL 1 2016

RECEIVED

NM OIL CONSERVATION
ARTESIA DISTRICT

JUN 28 2016

RECEIVED

Accepted For Record
NMOCD

14. I hereby certify that the foregoing is true and correct.

Electronic Submission #341834 verified by the BLM Well Information System
For CHEVRON USA INCORPORATED, sent to the Hobbs
Committed to AFMSS for processing by PRISCILLA PEREZ on 06/15/2016 (16PP0785SE)

Name (Printed/Typed) CINDY H MURILLO Title PERMITTING SPECIALIST

Signature (Electronic Submission) Date 06/13/2016

THIS SPACE FOR FEDERAL OR STATE OFFICE USE

Approved By [Signature] Title SAET Date 6-20-16

Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.

Office CFO

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

**** BLM REVISED ** BLM REVISED ** BLM REVISED ** BLM REVISED ** BLM REVISED ****

Accepted for Record Only
MUR/OCD 7/11/2016

In the process of scoping out the work at the Xion Federal #1 reclamation, a spill/leak was detected off the south side of the pad. The contaminated area is 900 ft from the wellhead of the Xion Federal #1, and 635 ft from the wellhead on the Xion Federal #2. The area in question is a roughly 30' by 30' area shown by the highlighted yellow box below.

Chevron will take a backhoe from the Xion Federal #2 out to the spill area and remove all the contaminated soil. Chevron will backfill the hole with caliche and soil, and then re-contour the area. Chevron will then return to work on reclaiming the Xion Federal #1.

Chevron has paid \$1,599 into the Permian Basin Programmatic Agreement. The check was sent on 6/1/2016, and the check number is 0025624592.



