

JUL 11 2016

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

RECEIVED

BRADENHEAD TEST REPORT

Operator Name OXY USA INC	API Number 30-025-07483
Property Name STATE LAND SECTION 30	Well No. 5

7. Surface Location

UL - Lot K	Section 30	Township 18-S	Range 38-E	Feet from 1980	N/S Line SOUTH	Feet From 1914	E/W Line WEST	County LEA
---------------	---------------	------------------	---------------	-------------------	-------------------	-------------------	------------------	---------------

Well Status

TA'D WELL ☒ YES ☐ NO	SHUT-IN ☒ YES ☐ NO	INJ	INJECTOR SWD	PRODUCER ☒ OIL ☐ GAS	DATE 20 June 16
--	--	-----	-----------------	--	--------------------

OBSERVED DATA

	(A)Surface	(B)Interm(1)	(C)Interm(2)	(D)Prod Csg	(E)Tubing
Pressure	Opsi			Opsi	Opsi
Flow Characteristics					
Puff	Y / N	Y / N	Y / N	Y / N	CO2 ___
Steady Flow	Y / N	Y / N	Y / N	Y / N	WTR ___
Surges	Y / N	Y / N	Y / N	Y / N	GAS ___
Down to nothing	Y / N	Y / N	Y / N	Y / N	Type of Fluid Injected for Waterflood if applies.
Gas or Oil	Y / N	Y / N	Y / N	Y / N	
Water	Y / N	Y / N	Y / N	Y / N	

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

A. Surface - No Puff to Nothing

Danre/Calvin
575-318-5067

Signature: <i>Mendy Johnson</i>	OIL CONSERVATION DIVISION
Printed name: MENDY JOHNSON	Entered into RBDMS
Title: ADMINISTRATIVE ASSOCIATE	Re-test
E-mail Address: mendy_johnson@oxy.com	
Date: JUL - 7 2016	
Phone: 806-592-6280	
Witness:	

INSTRUCTIONS ON BACK OF THIS FORM