

JUL 11 2016

RECEIVED

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

BRADENHEAD TEST REPORT

Operator Name OXY USA INC	API Number 30-025-07542
Property Name STATE LAND SECTION 32	Well No. 8

7. Surface Location

UL - Lot I	Section 32	Township 18-S	Range 38-E	Feet from 1980	N/S Line SOUTH	Feet From 660	E/W Line EAST	County LEA
---------------	---------------	------------------	---------------	-------------------	-------------------	------------------	------------------	---------------

Well Status

YES	NO	YES	NO	INJ	SWD	OIL	GAS	DATE 20 June 16
-----	----	-----	----	-----	-----	-----	-----	--------------------

OBSERVED DATA

	(A)Surface	(B)Interm(1)	(C)Interm(2)	(D)Prod Csg	(E)Tubing
Pressure	Ops!			Ops!	Ops!
Flow Characteristics					
Puff	Y / (N)	Y / N	Y / N	Y / N	CO2 ___
Steady Flow	Y / (N)	Y / N	Y / N	Y / N	WTR ___
Surges	Y / (N)	Y / N	Y / N	Y / N	GAS ___
Down to nothing	(Y) / N	Y / N	Y / N	Y / N	Type of Fluid
Gas or Oil	Y / (N)	Y / N	Y / N	Y / N	Injected for
Water	Y / (N)	Y / N	Y / N	Y / N	Waterflood if
					applies.

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

A. Surface - Puff to Nothing

Daniel Cohen
575-318.5067.

Signature: <i>Mendy Johnson</i>	OIL CONSERVATION DIVISION
Printed name: MENDY JOHNSON	Entered into RBDMS
Title: ADMINISTRATIVE ASSOCIATE	Re-test
E-mail Address: mendy_johnson@oxy.com	
Date: JUL - 7 2016	
Phone: 806-592-6280	
Witness:	

INSTRUCTIONS ON BACK OF THIS FORM