

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

JUL 25 2016

RECEIVED

BRADENHEAD TEST REPORT

Operator Name Chevron U.S.A, INC	³ API Number 3002523031
Property Name QUAIL QUEEN UNIT	Well No. 8

7. Surface Location									
UL - Lot K	Section 11	Township 19S	Range 34E		Feet from 2080	N/S Line S	Feet From 1980	E/W Line W	County LEA

Well Status

Well Status TA	SHUT-IN Yes	PRODUCING TA'D	DATE 7/11/16
-------------------	----------------	-------------------	-----------------

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

OBSERVED DATA

If bradenhead flowed water, check all of the descriptions that apply:


	(A)Surf-Prod	(B)Interm(1)-Interm(2)	(C)Interm-Prod	(D)Prod Csng	(E)Tubing
Pressure	0	NA	NA	0	0
Flow Characteristics					
Puff	Y / N	Y / N	Y / N	Y / N	
Steady Flow	Y / N	Y / N	Y / N	Y / N	
Surges	Y / 0	Y / N	Y / N	Y / 0	
Down to nothing	Y / N	Y / N	Y / N	Y / N	
Gas or Oil	Y / 0	Y / N	Y / N	Y / 0	
Water	Y / N	Y / N	Y / N	Y / N	

If bradenhead flowed water, check all of the descriptions that apply:

CLEAR	FRESH	SALTY	SULFUR	BLACK
-------	-------	-------	--------	-------

Remarks:

INJECTING AT THIS TIME ___ WTR, ___ GAS, ___ CO2

Signature: 	OIL CONSERVATION DIVISION
Printed name: CHRIS PHILLIPS	Entered into RBDMS
Title: PRODUCTION SPECIALIST SUB SURFACE	Re-test
E-mail Address: CPIV@CHEVRON.COM	
Date: 7/11/16	Phone: 307-705-6406
Witness:	