

JUL 25 2016

RECEIVED

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

BRADENHEAD TEST REPORT

Operator Name Chevron U.S.A, INC	³ API Number 3002526707
Property Name QUAIL QUEEN UNIT	Well No. 11

7. Surface Location

UL - Lot A	Section 11	Township 19S	Range 34E	Feet from 990	N/S Line N	Feet From 990	E/W Line E	County LEA
----------------------	----------------------	------------------------	---------------------	-------------------------	----------------------	-------------------------	----------------------	----------------------

Well Status

Well Status TA	SHUT-IN yes	PRODUCING TA'D	DATE 7/11/16
--------------------------	-----------------------	--------------------------	------------------------

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

OBSERVED DATA

If bradenhead flowed water, check all of the descriptions that apply:

	(A)Surf-Prod	(B)Interm(1)-Interm(2)	(C)Interm-Prod	(D)Prod Csgng	(E)Tubing
Pressure	☒	NA	NA	☒	☒
Flow Characteristics					
Puff	☒ / N	Y / N	Y / N	☒ / N	
Steady Flow	Y / ☒	Y / N	Y / N	Y / ☒	
Surges	Y / ☒	Y / N	Y / N	Y / ☒	
Down to nothing	☒ / N	Y / N	Y / N	☒ / N	
Gas or Oil	Y / ☒	Y / N	Y / N	Y / ☒	
Water	Y / ☒	Y / N	Y / N	Y / ☒	

If bradenhead flowed water, check all of the descriptions that apply:

CLEAR	FRESH	SALTY	SULFUR	BLACK
-------	-------	-------	--------	-------

Remarks:

INJECTING AT THIS TIME ___ WTR, ___ GAS, ___ CO2

Signature: 	OIL CONSERVATION DIVISION
Printed name: CHRIS PHILLIPS	Entered into RBDMS
Title: PRODUCTION SPECIALIST SUB SURFACE	Re-test
E-mail Address: CPIV@CHEVRON.COM	
Date: 7/11/16	
Phone: 307-705-6406	
Witness:	