Submit One Copy To Appropriate District State of New Mexico	Form C-103
Submit One Copy To Appropriate District Office District I 1625 N. French Dr., Hobbs, NM 88240 State of New Mexico Energy, Minerals and Natural Resources	Revised November 3, 2011 WELL API NO.
District II 811 S. First St., Artesia, NM 88210 AUG 01 2811 CONSERVATION DIVISION	30-025-01461 /
District III 1220 South St. Francis Dr.	5. Indicate Type of Lease STATE X FEE
District III 1000 Rio Brazos Rd., Aztec, NM 87410 District IV 1220 S. St. Francis Dr., Santa Fe, NM 87505	6. State Oil & Gas Lease No.
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH	7. Lease Name or Unit Agreement Name Caprock Maljamar Unit
PROPOSALS.) 1. Type of Well: X Oil Well Gas Well Other	8. Well Number 7
2. Name of Operator LINN	9. OGRID Number 269324
3. Address of Operator	10. Pool name or Wildcat
2130 West Bender Hobbs, N.M.	Maljamar Grayburg-SanAndres
4. Well Location	
Unit Letter <u>G</u> : <u>1980</u> feet from the <u>N</u> line and <u>2080</u> feet from the <u>E</u> line	
Section 18 Township 17S Range 33E NMPM County Lea	Control of the second second
11. Elevation (Show whether DR, RKB, RT, GR, etc.) 4210' GR	
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data	
NOTICE OF INTENTION TO	
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASING COMMENCE DRILLING OPNS. PAND A X	
TEMPORARILY ABANDON	
TOLE ON ALTER GAGING MOETH LE COMPLET DE CAGING/CEME	
	ready for OCD inspection after P&A
X All pits have been remediated in compliance with OCD rules and the terms of the Operator's pit permit and closure plan.	
X Rat hole and cellar have been filled and leveled. Cathodic protection holes have been properly abandoned.	
X A steel marker at least 4" in diameter and at least 4' above ground level has been set in concrete. It shows the	
OPERATOR NAME, LEASE NAME, WELL NUMBER, API NUMBER, QUARTER/QUARTER LOCATION OR	
UNIT LETTER, SECTION, TOWNSHIP, AND RANGE. All INFORMATION HAS BEEN WELDED OR	
PERMANENTLY STAMPED ON THE MARKER'S SURFACE.	
X The location has been leveled as nearly as possible to original ground contour and has been cleared of all junk, trash, flow lines and other production equipment.	
X Anchors, dead men, tie downs and risers have been cut off at least two feet below ground level.	
X If this is a one-well lease or last remaining well on lease, the battery and pit location(s) have been remediated in compliance with OCD	
rules and the terms of the Operator's pit permit and closure plan. All flow lines, production equipment and junk have been removed from	
lease and well location.	
X All metal bolts and other materials have been removed. Portable bases have been removed. (Poured onsite concrete bases do not have	
to be removed.) X All other environmental concerns have been addressed as per OCD rules.	
X Pipelines and flow lines have been abandoned in accordance with 19.15.35.10 NMAC. All fluids have been removed from non-	
retrieved flow lines and pipelines.	
☐ If this is a one-well lease or last remaining well on lease: all electrical service poles and lines have been removed from lease and well	
location, except for utility's distribution infrastructure. Lea County Electric Poles and Lines	
When all work has been completed, return this form to the appropriate District office to schedule an inspection.	
SIGNATURE TITLE Production Supervisor DATE 7-28-2016	
TYPE OR PRINT NAME Ex. Gonzales E-MAIL: elgonzales@linnenergy.com PHONE: 575-738-1739	

DATE 8/8/2016