

HOBBS OCD

AUG 08 2016

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

RECEIVED

BRADENHEAD TEST REPORT

Operator Name DKD, LLC		* API Number 30-025-34197 ✓
Property Name Watson 6 SWD		Well No. #1 ✓

7. Surface Location

U.L. - Lot 14	Section 6	Township 16S	Range 36E	Feet from 2857	N/S Line S	Feet From 1417	E/W Line W	County Lea
-------------------------	---------------------	------------------------	---------------------	--------------------------	----------------------	--------------------------	----------------------	----------------------

Well Status

YES	TA'D WELL NO	YES	SHUT-IN NO	INJ	INJECTOR SWD	OIL	PRODUCER	GAS	DATE 7-27-16
-----	------------------------	-----	----------------------	-----	------------------------	-----	----------	-----	------------------------

OBSERVED DATA

	(A)Surface	(B)Interm(1)	(C)Interm(2)	(D)Prod Csg	(E)Tubing
Pressure	0	0 NA	0 NA	0	0 (VAC)
Flow Characteristics					
Puff	Y/N	Y/N	Y/N	Y/N	CO2 —
Steady Flow	Y/N	Y/N	Y/N	Y/N	WTR X
Surges	Y/N	Y/N	Y/N	Y/N	GAS —
Down to nothing	Y/N	Y/N	Y/N	Y/N	Type of Fluid
Gas or Oil	Y/N	Y/N	Y/N	Y/N	Injected for
Water	Y/N	Y/N	Y/N	Y/N	Waterflood if
					applies.

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

NOTHING NO PUFF OR VAC

Signature: Danny R Watson		OIL CONSERVATION DIVISION	
Printed name: DANNY R WATSON		Entered into RBDMS MSB 8/8/2016	
Title: OWNER		Re-test	
E-mail Address:			
Date: 7/27/16	Phone: 575-369-5024		
Witness:			

INSTRUCTIONS ON BACK OF THIS FORM