

HOBBS OCD

AUG 08 2016

RECEIVED

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

BRADENHEAD TEST REPORT

Operator Name <i>Apache Corp</i>		API Number <i>300-25-37211</i>	
Property Name <i>Southern Sunflower 3 state #1</i>		Well No. <i>#1</i>	

Surface Location								
UL - Lot <i>0</i>	Section <i>03</i>	Township <i>18S</i>	Range <i>34E</i>	Feet from <i>1070</i>	N/S Line <i>EWL</i>	Feet From <i>1220</i>	E/W Line <i>EWL</i>	County <i>Lra</i>

Well Status					
TA'D WELL YES ☒ NO ☐	SHUT-IN YES ☐ NO ☐	INJ YES ☐ NO ☐	INJECTOR YES ☐ NO ☐	PRODUCER YES ☒ NO ☐	DATE <i>7-29-16</i>

OBSERVED DATA

	(A) Surface	(B) Interm(1)	(C) Interm(2)	(D) Prod Casing	(E) Tubing
Pressure	15	25	NA	40	150
Flow Characteristics					
Puff	Y/N	Y/N	Y/N	Y/N	CO2
Steady flow	Y/N	Y/N	Y/N	Y/N	WTR
Surges	Y/N	Y/N	Y/N	Y/N	GAS
Down to nothing	Y/N	Y/N	Y/N	Y/N	Type of Fluid
Gas or Oil	Y/N	Y/N	Y/N	Y/N	Injected for
Water	Y/N	Y/N	Y/N	Y/N	Waterflood if

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

Signature: <i>[Signature]</i>		OIL CONSERVATION DIVISION	
Printed name: <i>Eduardo Pizarro</i>		Entered into RBDMS	
Title: <i>pumper</i>		Re-test <i>[Signature]</i>	
E-mail Address: <i>Eduardo.Pizarro@apachecorp.com</i>			
Date: <i>7-29-16</i>	Phone:		
Witness:			