

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

AUG 15 2016

BRADENHEAD TEST REPORT

RECEIVED

Operator Name APACHE CORP	API Number 3002506344
Property Name NEDU	Well No. 114

7. Surface Location

UL Lot D	Section 2	Township 21S	Range 37E	Feet from 906	N/S Line N	Feet From 660	E/W Line W	County LEA
--------------------	---------------------	------------------------	---------------------	-------------------------	----------------------	-------------------------	----------------------	----------------------

Well Status

TA'D WELL YES ☒ NO ☐	SHUT-IN YES ☐ NO ☒	INJECTOR ☒ INJ	SWD	OIL	PRODUCER GAS	DATE 4-13-16
--	--	---	-----	-----	-----------------	------------------------

OBSERVED DATA

	(A)Surface	(B)Interm(1)	(C)Interm(2)	(D)Prod Csg	(E)Other
Pressure	20			20	1200
Flow Characteristics					
Puff	Y/N	Y/N	Y/N	Y/N	CO2
Steady Flow	Y/N	Y/N	Y/N	Y/N	WTR
Surges	Y/N	Y/N	Y/N	Y/N	GAS
Down to nothing	Y/N	Y/N	Y/N	Y/N	Type of Fluid
Gas or Oil	Y/N	Y/N	Y/N	Y/N	Injected for
Water	Y/N	Y/N	Y/N	Y/N	Waterflood if applies

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

Signature: DAVID CUMMINGS	OIL CONSERVATION DIVISION
Printed name: DAVID CUMMINGS	Entered into RBDMS
Title: SR PUMPER	Re-test [Signature]
E-mail Address:	
Date: 4-13-16	
Phone:	
Witness: Kristi Needy	