

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

HOBBS OCD

AUG 12 2008

RECEIVED

BRADENHEAD TEST REPORT

Operator Name APACHE CORP	API Number 30 025 06351
Property Name NEDU	Well No. ZZ 4

7. Surface Location

U/L - Lot 5	Section 2	Township 21 6	Range 37 E	Feet from 4303	N/S Line S	Feet From 2317	E/W Line E	County LEA
-----------------------	---------------------	-------------------------	----------------------	--------------------------	----------------------	--------------------------	----------------------	----------------------

Well Status

TA'D WELL YES	NO	SHUT-IN YES	NO	INJECTOR INJ	SWD	OIL	PRODUCER GAS	DATE 4-11-16
-------------------------	-----------	-----------------------	-----------	------------------------	-----	-----	------------------------	------------------------



OBSERVED DATA

	(A) Surface	(B) Intern. (1)	(C) Intern. (2)	(D) Prod Casing	(E) Tubing
Pressure	0			0	1100
Flow Characteristics					
Full	(Y) N	Y / N	Y / N	Y / N	CO2
Steady Flow	Y / (N)	Y / N	Y / N	Y / N	WTR
Surges	Y / (N)	Y / N	Y / N	Y / N	GAS
Down to nothing	(Y) N	Y / N	Y / N	(Y) N	Type of Fluid
Gas or Oil	Y / (N)	Y / N	Y / N	Y / N	Injected for
Water	Y / (N)	Y / N	Y / N	Y / N	Waterflood if
					applies.

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

SO2 BLEED DOWN ABOUT 1.5 MIN

K.H. Witness

Signature: 	OIL CONSERVATION DIVISION
Printed name: DAVID CUMMINGS	Entered into RBDMS
Title: 	Re-test 
E-mail Address:	
Date:	Phone:
	Witness: