

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

AUG 12 2016

RECEIVED

BRADENHEAD TEST REPORT

Operator Name APACHE CORP	API Number 30 025 06495
Property Name XEDU	Well No. 110

7. Surface Location

UL - Lot 6	Section 3	Township 21S	Range 37E	Feet from 1980	N/S Line N	Feet From 1980	E/W Line E	County LEA
----------------------	---------------------	------------------------	---------------------	--------------------------	----------------------	--------------------------	----------------------	----------------------

Well Status

YES TA'D WELL YES	NO NO	YES SHUT-IN NO	NO NO	INJECTOR INJ	SWD	OIL PRODUCER OIL	GAS	DATE 4-13-16
-----------------------------	-----------------	--------------------------	-----------------	------------------------	-----	----------------------------	-----	------------------------

OBSERVED DATA

	(A) Surface	(B) Interm(1)	(C) Interm(2)	(D) Prod Case	(E) Flow
Pressure	1200				1200
Flow Characteristics					
Steady	Y/N	Y/N	Y/N	Y/N	
Surge	Y/N	Y/N	Y/N	Y/N	
Down to nothing	Y/N	Y/N	Y/N	Y/N	
Gas or Oil	Y/N	Y/N	Y/N	Y/N	
Water	Y/N	Y/N	Y/N	Y/N	

Remarks: Please copy from columns (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

Signature: DAVID CUMMINGS	OIL CONSERVATION DIVISION
Printed name: DAVID CUMMINGS	Entered into RBDMS
Title: SR PUMPER	Re-test mb
E-mail Address:	
Date: 4-13-16	
Phone:	
Witness: Kristen Heady	