

AUG 12 2016

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

RECEIVED

BRADENHEAD TEST REPORT

Operator Name APACHE	API Number 30 025 06465
Property Name NEDU	Well No. 506

7. Surface Location

UL - Lot 0	Section 10	Township 21S	Range 37E	Feet from 660	N/S Line S	Feet From 1980	E/W Line E	County LEA
----------------------	----------------------	------------------------	---------------------	-------------------------	----------------------	--------------------------	----------------------	----------------------



Well Status

YES ☒ TA'D WELL	NO ☐	YES ☐	SHUT-IN ☒	NO ☐	INJ ☐	INJECTOR	SWD	OIL	PRODUCER	GAS	DATE 4-28-16
---	-----------------------------	------------------------------	---	-----------------------------	------------------------------	----------	-----	-----	----------	-----	------------------------

OBSERVED DATA

	(A)Surface	(B)Interm(1)	(C)Interm(2)	(D)Prod Csg	(E)Tubing
Pressure	☒			☒	☒
Flow Characteristics					
Puff	Y / ☐ N	Y / N	Y / N	☐ Y / ☒ N	CO2 —
Steady Flow	Y / ☐ N	Y / N	Y / N	Y / ☐ N	WTR —
Surges	Y / ☐ N	Y / N	Y / N	Y / ☐ N	GAS —
Down to nothing	Y / ☐ N	Y / N	Y / N	☐ Y / ☒ N	Type of Fluid
Gas or Oil	Y / ☐ N	Y / N	Y / N	Y / ☐ N	Injected for
Water	Y / ☐ N	Y / N	Y / N	Y / ☐ N	Waterflood if
					applies.

Remarks – Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

Signature: 	OIL CONSERVATION DIVISION
Printed name: DAVID CUMMINGS	Entered into RBDMS
Title: SR PUMPER	Re-test 
E-mail Address:	
Date:	Phone:
	Witness: