

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

AUG 12 2016

BRADENHEAD TEST REPORT

RECEIVED

Operator Name APACHE CORP	API Number 30 025 06771
Property Name NEDU	Well No. 811

7. Surface Location

UL - Lot 2	Section 23	Township 21S	Range 37E	Feet from 1980	N/S Line N	Feet From 660	E/W Line W	County LEA
----------------------	----------------------	------------------------	---------------------	--------------------------	----------------------	-------------------------	----------------------	----------------------

Well Status

TA'D WELL YES	☒ NO	☒ YES	SHUT-IN ☒ NO	☒ INJ	INJECTOR SWD	PRODUCER OIL	GAS	DATE 5-3-16
------------------	-------------------------------------	--------------------------------------	--	--------------------------------------	-----------------	-----------------	-----	-----------------------

OBSERVED DATA

	(A)Surface	(B)Interm(1)	(C)Interm(2)	(D)Prod Csg	(E)Tubing
Pressure	D	D		D	D
Flow Characteristics					
Puff	Y / ☒ N	Y / ☒ N	Y / N	Y / ☒ N	CO2 —
Steady Flow	Y / ☒ N	Y / ☒ N	Y / N	Y / ☒ N	WTR —
Surges	Y / ☒ N	Y / ☒ N	Y / N	Y / ☒ N	GAS —
Down to nothing	Y / ☒ N	Y / ☒ N	Y / N	Y / ☒ N	Type of Fluid
Gas or Oil	Y / ☒ N	Y / ☒ N	Y / N	Y / ☒ N	Injected for
Water	Y / ☒ N	Y / ☒ N	Y / N	Y / ☒ N	Waterflood if applies.

Remarks – Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

Signature: David Cummings	OIL CONSERVATION DIVISION
Printed name: DAVID CUMMINGS	Entered into RBDMS
Title: SR PUMPER	Re-test ms
E-mail Address:	
Date:	Phone:
Witness:	