

AUG 24 2016

RECEIVED

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

BRADENHEAD TEST REPORT

Operator Name APACHE CORP		API Number 30 025 06353	
Property Name NEDU		Well No. 319	

7. Surface Location

UL - Lot Q	Section 2	Township 21S	Range 31E	Feet from 1650	N/S Line S	Feet From 990	E/W Line E	County LEA
----------------------	---------------------	------------------------	---------------------	--------------------------	----------------------	-------------------------	----------------------	----------------------



Well Status

TA'D WELL YES ☒ NO ☐	SHUT-IN YES ☒ NO ☐	INJECTOR ☒ INJ ☐ SWD	PRODUCER OIL ☒ GAS ☐	DATE 8-15-16
--	--	--	--	------------------------

OBSERVED DATA

	(A)Surface	(B)Interm(1)	(C)Interm(2)	(D)Prod Csg	(E)Tubing
Pressure	0	0		0	1260
Flow Characteristics					
Puff	Y / ☒ N	☒ Y / N	Y / N	☒ Y / N	CO2 ___
Steady Flow	Y / ☒ N	Y / ☒ N	Y / N	Y / ☒ N	WTR ___
Surges	Y / ☒ N	Y / ☒ N	Y / N	☒ Y / N	GAS ___
Down to nothing	☒ Y / ☒ N	☒ Y / N	Y / N	☒ Y / N	Type of Fluid
Gas or Oil	Y / ☒ N	Y / ☒ N	Y / N	☒ Y / N	Injected for
Water	Y / ☒ N	Y / ☒ N	Y / N	Y / ☒ N	Waterflood if applies.

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

Signature: 		OIL CONSERVATION DIVISION	
Printed name: DAVID CUMMINGS		Entered into RBDMS	
Title: SR PUMPER		Re-test 	
E-mail Address:			
Date:	Phone:		
	Witness:		