

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

AUG 24 2016

RECEIVED

BRADENHEAD TEST REPORT

Operator Name APACHE CORP	API Number 3002506772
Property Name NEDU	Well No. 813

7. Surface Location

UL - Lot F	Section 23	Township T21S	Range 37E	Feet from 1980	N/S Line N	Feet From 1980	E/W Line W	County LEA
----------------------	----------------------	-------------------------	---------------------	--------------------------	----------------------	--------------------------	----------------------	----------------------

Well Status

TA'D WELL YES	NO	SHUT-IN YES	NO	INJECTOR INJ	SWD	OIL	PRODUCER	GAS	DATE 8-15-16
-------------------------	-----------	-----------------------	-----------	------------------------	-----	-----	----------	-----	------------------------

OBSERVED DATA

	(A)Surface	(B)Interm(1)	(C)Interm(2)	(D)Prod Csng	(E)Tubing
Pressure	0	0		YES	1150
Flow Characteristics					
Puff	Y / N	Y / N	Y / N	Y / N	CO2 ___
Steady Flow	Y / N	Y / N	Y / N	Y / N	WTR ___
Surges	Y / N	Y / N	Y / N	Y / N	GAS ___
Down to nothing	Y / N	Y / N	Y / N	Y / N	Type of Fluid
Gas or Oil	Y / N	Y / N	Y / N	Y / N	Injected for
Water	Y / N	Y / N	Y / N	Y / N	Waterflood if
					applies.

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

PROD BLEED OFF 5 SEC ✓

Signature: [Signature]	OIL CONSERVATION DIVISION
Printed name: DAVID CUMMINGS	Entered into RBDMS
Title: SR PUMPER	Re-test
E-mail Address:	
Date:	
Phone:	
Witness:	