

AUG 29 2016

RECEIVED

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

BRADENHEAD TEST REPORT

Operator Name EOG Resources, Inc.	API Number 30-025-30683
Property Name West Corbin Fed	Well No. 16

Surface Location

UL - Lot 0	Section 7	Township 18S	Range 33E	Feet from 800'	N/S Line South	Feet from 1980'	E/W Line East	County Lea
---------------	--------------	-----------------	--------------	-------------------	-------------------	--------------------	------------------	---------------

Well Status

Well Status Active	SHUT-IN Active	PRODUCING SWD	DATE 8/15/2016
-----------------------	-------------------	------------------	-------------------

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

OBSERVED DATA

If bradenhead flowed water, check all of the descriptions that apply:

	(A)Surf-Interm	(B)Interm(1)-Interm(2)	(C)Interm-Prod	(D)Prod Casing	(E)Tubing
Pressure	0		0	0	1300
Flow Characteristics					
Puff	Y / N	Y / N	Y / N	Y / N	
Steady Flow	Y / N	Y / N	Y / N	Y / N	
Surges	Y / N	Y / N	Y / N	Y / N	
Down to nothing	Y / N	Y / N	Y / N	Y / N	
Gas or Oil	Y / N	Y / N	Y / N	Y / N	
Water	Y / N	Y / N	Y / N	Y / N	

If bradenhead flowed water, check all of the descriptions that apply:

CLEAR	FRESH	SALTY	SULFUR	BLACK
-------	-------	-------	--------	-------

Remarks:

- (A) Opened valve, slight puff. Tested for 15 minutes.
(C) Opened valve, slight puff. Tested for 15 minutes.
(D) Opened valve, slight puff. Tested for 15 minutes.
Injection pump was running during test.

Field information submitted by Candy Aguilar.

Signature: Stan Wagner	OIL CONSERVATION DIVISION
Printed name: Stan Wagner	Entered into RBDMS
Title: Regulatory Analyst	Re-test
E-mail Address: stan.wagner@eogresources.com	
Date: 8/25/16	
Phone: 432-686-3689	
Witness:	