

HOBBS OCD

AUG 29 2016

RECEIVED

State of New Mexico  
Energy, Minerals and Natural Resources Department  
Oil Conservation Division Hobbs District Office

BRADENHEAD TEST REPORT

Operator Name EOG Resources, Inc.	API Number 30-025-32915
Property Name East Corbin Delaware Unit	Well No. 9

2. Surface Location

UL - Lot H	Section 21	Township 18S	Range 33E	Feet from 1340'	N/S Line North	Feet from 990'	E/W Line East	County Lea
---------------	---------------	-----------------	--------------	--------------------	-------------------	-------------------	------------------	---------------

Well Status

Well Status	SHUT-IN Active	PRODUCING Injection	DATE 8/13/2016
-------------	-------------------	------------------------	-------------------

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

OBSERVED DATA

If bradenhead flowed water, check all of the descriptions that apply:

	(A) Surf-Interm	(B) Interm (1)-Interm (2)	(C) Interm-Prod	(D) Prod Casing	(E) Tubing
Pressure	0		0	0	1290
Flow Characteristics					
Puff	Y / N	Y / N	Y / N	Y / N	
Steady Flow	Y / N	Y / N	Y / N	Y / N	
Surges	Y / N	Y / N	Y / N	Y / N	
Down to nothing	Y / N	Y / N	Y / N	Y / N	
Gas or Oil	Y / N	Y / N	Y / N	Y / N	
Water	Y / N	Y / N	Y / N	Y / N	


If bradenhead flowed water, check all of the descriptions that apply:

CLEAR	FRESH	SALTY	SULFUR	BLACK
-------	-------	-------	--------	-------

Remarks:

(A) Opened valve, slight puff. Tested for 15 minutes.  
(C) Opened valve, slight puff. Tested for 15 minutes.  
(D) Opened valve, slight puff. Flowed 1/2 gallon of black fluid for 20 seconds and stopped. Tested for 15 minutes.  
Injection pump was running during test.

Field information submitted by Candy Aguilar.

Signature: 	OIL CONSERVATION DIVISION
Printed name: Stan Wagner	Entered into RBDMS
Title: Regulatory Analyst	Re-test
E-mail Address: stan.wagner@eogresources.com	
Date: 8/25/16	
Phone: 432-686-3689	
Witness:	