

HOBBS OCD

District I
1625 N. French Dr., Hobbs, NM 88240
Phone: (575) 393-6161 Fax: (575) 393-0720

OCT 04 2016

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

RECEIVED

BRADENHEAD TEST REPORT

Operator Name APACHE CORP		API Number 80 025 09932	
Property Name NEDU		Well No. 913	

7. Surface Location

UL - Lot K	Section 23	Township 25	Range 31E	Feet from 1980	N/S Line S	Feet From 1980	E/W Line W	County LEA
----------------------	----------------------	-----------------------	---------------------	--------------------------	----------------------	--------------------------	----------------------	----------------------

Well Status

TA'D WELL YES	NO	YES	SHUT-IN NO	INJ	INJECTOR NO	SWD	OIL	PRODUCER NO	GAS	DATE 8-15-16
-------------------------	-----------	------------	----------------------	------------	-----------------------	-----	-----	-----------------------	-----	------------------------

OBSERVED DATA

	(A)Surface	(B)Interm(1)	(C)Interm(2)	(D)Prod Csg	(E)Tubing
Pressure			300	0	0
Flow Characteristics					
Puff	Y / N	Y / N	Y / N	Y / (N)	CO2 —
Steady Flow	Y / N	Y / N	Y / N	Y / (N)	WTR —
Surges	Y / N	Y / N	Y / N	Y / (N)	GAS —
Down to nothing	Y / N	Y / N	Y / N	(Y) N	Type of fluid injected for waterflood if applicable
Gas or Oil	Y / N	Y / N	Y / N	Y / (N)	
Water	Y / N	Y / N	Y / N	Y / (N)	

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

**SURF BLED DOWN 2 MIN - BUILDS UP
SHUTIN .
SI**

**Failure
Letter
Sent**

Signature: [Signature]		OIL CONSERVATION DIVISION	
Printed name: DAVID CUMMINGS		Entered into RBDMS	
Title: SR PUMPER		Re-test	
E-mail Address:		[Signature]	
Date:	Phone:		
	Witness:		