

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

BRADENHEAD TEST REPORT

Operator Name LINN OPERATING	API Number 30-025-01457
Property Name CAPROCK MALJAMAR UNIT	Well No. 18

2. Surface Location									
UL - Lot	Section	Township	Range		Feet from	N/S Line	Feet From	E/W Line	County
	18	17S	33E						

Well Status									
TA'D WELL		SHUT-IN		INJECTOR		PRODUCER		DATE	
YES	NO	YES	NO	INJ	SWD	OIL	GAS		

OBSERVED DATA

	(A)Surface	(B)Interm(1)	(C)Interm(2)	(D)Prod Csg	(E)Tubing
Pressure					
Flow Characteristics					
Puff	Y / N	Y / N	Y / N	Y / N	CO2 ___
Steady Flow	Y / N	Y / N	Y / N	Y / N	WTR ___
Surges	Y / N	Y / N	Y / N	Y / N	GAS ___
Down to nothing	Y / N	Y / N	Y / N	Y / N	Type of Fluid
Gas or Oil	Y / N	Y / N	Y / N	Y / N	Injected for
Water	Y / N	Y / N	Y / N	Y / N	Waterflood if
					applies.

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

Plugged
Failure 2.

Leaky
Seal

Signature: Eddie J. Jaramillo	OIL CONSERVATION DIVISION	
Printed name: Eddie J. Jaramillo	Entered into RBDMS	
Title: PRODUCTION SPECIALIST	Re-test	
E-mail Address:		
Date:	Phone: (575) 370-9686	
Witness:		

INSTRUCTIONS ON BACK OF THIS FORM