

JUN 20 2016

RECEIVED

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

BRADENHEAD TEST REPORT

Operator Name OCCIDENTAL PERMIAN, LTD	API Number 30-025-28413
Property Name NORTH HOBBS (G/SA) UNIT	Well No. 242

7. Surface Location

UL - Lot N	Section 29	Township 18-S	Range 38-E	Feet from 100	N/S Line SOUTH	Feet From 1400	E/W Line WEST	County LEA
---------------	---------------	------------------	---------------	------------------	-------------------	-------------------	------------------	---------------

Well Status

TA'D WELL YES	SHUT-IN YES	INJECTOR (INJ)	PRODUCER OIL	GAS	DATE 5/20/16
------------------	----------------	-------------------	-----------------	-----	-----------------

OBSERVED DATA

	(A)Surface	(B)Interm(1)	(C)Interm(2)	(D)Prod Csg	(E)Tubing
Pressure	G	800	N/A	343	992
Flow Characteristics					
Puff	Y / N	Y / N	Y / N	Y / N	CO2 —
Steady Flow	Y / N	N / N	Y / N	N / N	WTR ✓
Surges	Y / N	Y / N	Y / N	Y / N	GAS —
Down to nothing	N / N	N / N	Y / N	Y / N	Type of Fluid
Gas or Oil	Y / N	N / N	Y / N	Y / N	Injected for
Water	Y / N	Y / N	Y / N	N / N	Waterflood if
					applies.

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

(B) Bled down to zero in 10 sec. steady gas

(D) Bled down to zero in 8 sec. then pressured back to 100 psi - steady water
would not bleed down below 100 psi.

Failure
Operator Reported

Donna Higgins 575-631-9886

Signature: <i>Mendy Johnson</i>	OIL CONSERVATION DIVISION
Printed name: MENDY JOHNSON	Entered into RBDMS
Title: ADMINISTRATIVE ASSOCIATE	Re-test
E-mail Address: mendy_johnson@oxy.com	
Date: MAY 27 2016	
Phone: 806-592-6280	
Witness:	

INSTRUCTIONS ON BACK OF THIS FORM