

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

BRADENHEAD TEST REPORT

Operator Name MESQUITE SWD INC		API Number 30-025-27616
Property Name PADUCA SWD		Well No. 1

2. Surface Location

UL - Lot H	Section 22	Township 25S	Range 32E	Feet from 1480	N/S Line N	Feet From 660	E/W Line FEL	County LEA
----------------------	----------------------	------------------------	---------------------	--------------------------	----------------------	-------------------------	------------------------	----------------------

Well Status

YES TA'D WELL ☒	NO ☐	YES SHUT-IN ☐	NO ☐	INJ ☐	INJECTOR SWD	OIL PRODUCER ☐	GAS ☐	DATE 12/14/2016
--	--------------------------------	---	--------------------------------	---------------------------------	------------------------	--	---------------------------------	---------------------------

OBSERVED DATA

	(A) Surface	(B) Interim (1)	(C) Interim (2)	(D) Prod Casing	(E) Tubing
Pressure	0	M	—	0	800
Flow Characteristics					
Puff	Y/N	Y/N	Y/N	Y/N	CO2 —
Steady Flow	Y/N	Y/N	Y/N	Y/N	WTR —
Surges	Y/N	Y/N	Y/N	Y/N	GAS —
Down to nothing	Y/N	Y/N	Y/N	Y/N	Type of Fluid Injected for Waterflood if applicable
Gas or Oil	Y/N	Y/N	Y/N	Y/N	
Water	Y/N	Y/N	Y/N	Y/N	

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

Signature: Chris Sutton	OIL CONSERVATION DIVISION
Printed name: CHRIS LUTHERSON	Entered into RBDMS
Title: Production	Re-test —
E-mail Address: CHRIS.LUTHERSON@HOTMAIL.COM	
Date: 12/15/2016	
Phone: 575-706-1840	
Witness:	

HOBBS OOD
DEC 21 2016
RECEIVED