

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

BRADENHEAD TEST REPORT

Operator Name MESQUITE SWD INC		API Number 30-025-40813
Property Name PAOLUCA SWD #2		Well No. 2

Surface Location

UL - Lot 0	Section 22	Township 25	Range 32	Feet from 500	NS Line 5	Feet From 2000	E/W Line E	County LHA
----------------------	----------------------	-----------------------	--------------------	-------------------------	---------------------	--------------------------	----------------------	----------------------

Well Status

TA'D WELL YES ☒ NO ☒	SHUT-IN YES ☒ NO ☒	INJ ☒	INJECTOR SWD	OIL ☒	PRODUCER GAS ☒	DATE 12/14/2016
---	---	---	------------------------	---	--	---------------------------

OBSERVED DATA

	(A)Surface	(B)Interm(1)	(C)Interm(2)	(D)Prod Casing	(E)Tubing
Pressure	0	N/A	N/A	0	800"
Flow Characteristics					
Puff	Y/N ☒	Y/N ☒	Y/N ☒	Y/N ☒	CO2 ☒
Steady Flow	Y/N ☒	Y/N ☒	Y/N ☒	Y/N ☒	WTR ☒
Surges	Y/N ☒	Y/N ☒	Y/N ☒	Y/N ☒	GAS ☒
Down to nothing	Y/N ☒	Y/N ☒	Y/N ☒	Y/N ☒	Type of Fluid Indicated for Waterflood if applies.
Gas or Oil	Y/N ☒	Y/N ☒	Y/N ☒	Y/N ☒	
Water	Y/N ☒	Y/N ☒	Y/N ☒	Y/N ☒	

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

Signature: Clay L. Wilson		OIL CONSERVATION DIVISION	
Printed name: Clay L. Wilson		Entered into RBDMS	
Title: President		Re-test	
E-mail Address:			
Date: 12/15/2016	Phone: 575-706-1940		
Witness:			