

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

BRADENHEAD TEST REPORT

Operator Name <u>Black Mountain</u>		API Number <u>30-025-29808</u>
Property Name <u>Madera A 25 #1 SWD</u>		Well No. <u>#1</u>

1. Surface Location								
UL - Lot <u>1980</u>	Section <u>25</u>	Township <u>12N</u>	Range <u>R34E</u>	Feet from <u>1980</u>	N/S Line <u>S</u>	Feet from <u>1980</u>	E/W Line <u>E</u>	County <u>Lea</u>

Well Status		DATE <u>12-16-2016</u>	
TA'D WELL ☒ YES ☐ NO	SHUT-IN ☐ YES ☒ NO	INJ ☐ YES ☒ NO	PRODUCER ☒ OIL ☐ GAS

OBSERVED DATA

	(A)Surface	(B)Interm(1)	(C)Interm(2)	(D)Prod Csmg	(E)Tubing
Pressure	<u>φ</u>	<u>φ</u>		<u>φ</u>	<u>φ</u>
Flow Characteristics					
Full	☒ Y ☐ N	☒ Y ☐ N	Y / N	☒ Y ☐ N	CO2 ☐
Steady Flow	Y / N	Y / N	Y / N	Y / N	WTR ☒
Surges	Y / N	Y / N	Y / N	Y / N	GAS ☐
Down to nothing	Y / N	Y / N	Y / N	Y / N	Type of Fluid Injected for Waterflood if applicable
Gas or Oil	Y / N	Y / N	Y / N	Y / N	
Water	Y / N	Y / N	Y / N	Y / N	

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

Surface = open Quick Blow down
Interm = open Quick Blow down
Case = Blow down 35 sec.

Signature: <u>Joh H Lintz</u>	OIL CONSERVATION DIVISION
Printed name: <u>Joh H Lintz Sr.</u>	Entered into RBDMS
Title: <u>Pumper</u>	Re-test <u>[Signature]</u>
E-mail Address: <u>slw32@jsh400.com</u>	
Date: <u>12-20-2016</u>	Phone: <u>575-302-6080</u>
Witness:	

HOBBS OCD

DEC 28 2016

RECEIVED