

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

HOBBS OCD

JAN 09 2017

RECEIVED

BRADENHEAD TEST REPORT

Operator Name CROSS BORDER RESOURCES		API Number 30-005-20686-0000	
Property Name TOM 36 STATE		Well No. 001H	

7. Surface Location

UL - Lot	Section	Township	Range	Feet from	N/S Line	Feet From	E/W Line	County
A	36	7-S	31-E	660	N	660	E	CHAVES

Well Status

TA'D Well YES ☒ NO	SHUT-IN YES ☒ NO	INJECTOR INJ ☒ SWD	PRODUCER OIL ☐ GAS ☐	DATE 1-9-17
---	---	---	---	-----------------------

OBSERVED DATA

	(A)Surf-Interm	(B)Interm(1)	(C)Interm(2)	(D)Prod Csg	(E)Tubing
Pressure					
Flow Characteristics					
Puff	Y / N	Y / N	Y / N	Y / N	CO2 _____
Steady Flow	Y / N	Y / N	Y / N	Y / N	WTR _____
Surges	Y / N	Y / N	Y / N	Y / N	GAS _____
Down to nothing	Y / N	Y / N	Y / N	Y / N	If applicable type
Gas or Oil	Y / N	Y / N	Y / N	Y / N	fluid injected for
Water	Y / N	Y / N	Y / N	Y / N	Waterflood

Remarks: Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

operator conceded Failure Hole in tubing

Failure

Signature: 		OIL CONSERVATION DIVISION
Printed name:		Entered into RBDMS
Title:		Re-test
E-mail Address:		
Date: 1-9-17	Phone:	
Witness: KERRY FORTNER-OCD 575-399-3221		

Kerry Fortner