NM OIL CONSERVATION

HOBBS OCD

ARTESIA DISTRICT

Office		exico 2 1 2017	Form C-103	
District I Energy, Mineral			Revised November 3, 2011	٦
1625 N. French Dr., Hobbs, NM 88240 District II 811 S. First St., Artesia, NM 88210 RECEIVED CONSER	NATION	RECEIVED	WELL API NO. 30-025-35634	
	th St. Fran		5. Indicate Type of Lease	
1000 Pio Brazos Pd. Aztec. NM 97410			STATE FEE	1
District IV 1220 S. St. Francis Dr., Santa Fe, NM	Fe, NM 87	7303	6. State Oil & Gas Lease No.	
87505			NM 648	
SUNDRY NOTICES AND REPORTS			7. Lease Name or Unit Agreement Name	
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH			TORO 22 STATE	
PROPOSALS.)			8. Well Number 004	+
1. Type of Well: Oil Well Gas Well Other				+
2. Name of Operator RKI EXPLORATION & PRODUCTION, LLC			9. OGRID Number 246289	
3. Address of Operator 3500 ONE WILLIAMS CENTER MD 35			10. Pool name or Wildcat	
TULSA, OK 74172			SHARB; DELAWARE	1
4. Well Location				
Unit Letter F: 1650 feet from the N				
Section 22 Township 19S Range 35E NMPM County LEA				
11. Elevation (Show to	whether DR,	RKB, RT, GR, etc.)		
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data				
NOTICE OF INTENTION TO:		SUBS	SEQUENT REPORT OF:	
PERFORM REMEDIAL WORK PLUG AND ABANDO	ON 🗆	REMEDIAL WORK		
TEMPORARILY ABANDON		COMMENCE DRIL	LING OPNS. P AND A	
PULL OR ALTER CASING MULTIPLE COMPL		CASING/CEMENT	JOB	1
OTHER:		☑ Location is ro	ady for OCD inspection after P&A	/
All pits have been remediated in compliance with OCD	rules and the			-
Rat hole and cellar have been filled and leveled. Catho				
A steel marker at least 4" in diameter and at least 4' about	ove ground	level has been set in	concrete. It shows the	
OPEDATOD NAME LEASE NAME WELL N	HIMDED A	DI NUMBER OU	A DTED OUA DTED LOCATION OD	
OPERATOR NAME, LEASE NAME, WELL NUMBER, API NUMBER, QUARTER/QUARTER LOCATION OR UNIT LETTER, SECTION, TOWNSHIP, AND RANGE. All INFORMATION HAS BEEN WELDED OR				
PERMANENTLY STAMPED ON THE MARKER'S SURFACE.				
■ The location has been leveled as nearly as possible to original ground contour and has been cleared of all junk, trash, flow lines and other production equipment.				
Anchors, dead men, tie downs and risers have been cut off at least two feet below ground level.				
If this is a one-well lease or last remaining well on lease, the battery and pit location(s) have been remediated in compliance with				
OCD rules and the terms of the Operator's pit permit and clo	osure plan.	All flow lines, produ	iction equipment and junk have been remove	d
from lease and well location. All metal bolts and other materials have been removed.	Dortoble he	sas hava baan ramay	and (Poured ansite concrete bases do not have	0
to be removed.)	Portable ba	ses have been remov	red. (Foured offsite concrete bases do not have	0
All other environmental concerns have been addressed	as per OCD	rules.		
Pipelines and flow lines have been abandoned in accord	dance with 1	9.15.35.10 NMAC.	All fluids have been removed from non-	
retrieved flow lines and pipelines.			10	
If this is a one-well lease or last remaining well on least location, except for utility's distribution infrastructure.	e: all electric	cal service poles and	lines have been removed from lease and well	I
location, except for unity's distribution infrastructure.				
When all work has been completed, return this form to the a	ppropriate I	District office to sche	edule an inspection.	
SIGNATURE CANTO O'lh	_ _{TITLE} Pe	ermit Technici	an II	7
TYPE OR PRINT NAME Caitlin O'Hair	E-MAIL:	caitlin.ohair@wr	exenergy.com PHONE: 539-573-3527	
For State Use Only				
APPROVED BY Wash Cutifulan	TITLE 7	E.S.	DATE 02/21/201	7