FLARE INSPECTION

Devox LEASE OR FACILITY	NAME <u>Ne</u>	w Mexic	o Fed.	
WELL #/	AP	I# 30- <i>025</i>	- 29605	
U.L. H SEC 29	F_T	185	R 33E	
FOOTAGE 2080	<i>D</i> / s	600		
IS A FLARE STACK PR	ESENT?	YES	NO	
IS FLARE ACTIVE?	×	YES	NO	
IS GAS TO FLARE ME	TERED?	YES	NO	
AREA AROUND FLARE	CLEARED?	YES	NO	
ENVIRONMENTAL CO	NCERNS			
IS VRU PRESENT?		YES	NO	
IS VRU ACTIVE?		YES	NO	
COMMENTS				
el.	1/2/		2017	