FLARE INSPECTION

EDG
LEASE OR FACILITY NAME Jack Tank & Frd.
WELL # Z API# 30-025 - 32192
U.L. E SEC 8 T 245 R 326
FOOTAGE 2180 (DIS 660 EIW)
IS A FLARE STACK PRESENT? YES NO
IS FLARE ACTIVE? YES NO
IS GAS TO FLARE METERED? YES NO
AREA AROUND FLARE CLEARED? YES NO
ENVIRONMENTAL CONCERNS
IS VRU PRESENT? YES NO
IS VRU ACTIVE? YES NO
COMMENTS
THEORETON Mary Maleran 1 2-13-17