

FLARE INSPECTION

Devon

LEASE OR FACILITY NAME Bell Lake 19 State

WELL # 1H API# 30-025 - 41024

U.L. 17 SEC 19 T 24s R 33E

FOOTAGE 200 N 15 700 E 1W

IS A FLARE STACK PRESENT? ☒ YES ☐ NO

IS FLARE ACTIVE? YES ☒ NO

IS GAS TO FLARE METERED? ☒ YES ☐ NO

AREA AROUND FLARE CLEARED? ☒ YES ☐ NO

ENVIRONMENTAL CONCERNS _____

IS VRU PRESENT? ☒ YES ☐ NO

IS VRU ACTIVE? ☒ YES ☐ NO

COMMENTS _____

INSPECTOR Gary Robinson DATE 3-13-17