FLARE INSPECTION

Merchinson	
LEASE OR FACILITY	VAME Jackson Unit
WELL# 22H	API# 30- <u>025 - 41228</u>
U.L. <u>M</u> SEC 23	T 24's R 37E
FOOTAGE 200	NIS 350 EIW
IS A FLARE STACK PR	ESENT? YES NO
IS FLARE ACTIVE?	(YES) NO
IS GAS TO FLARE ME	TERED? YES NO
AREA AROUND FLARE	CLEARED? YES NO
ENVIRONMENTAL CO	NCERNS Las of of Versels meteril to comp
by pass or other	line to place + burning.
IS VRU PRESENT?	YES NO
IS VRU ACTIVE?	YES NO
COMMENTS Has	Mare on Japan gas
	11
INSPECTOR Lang	DATE 3-13-17