

HOBBS OCD

MAR 22 2017

RECEIVED

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

BRADENHEAD TEST REPORT

Operator Name oxy		API Number 3-025-05534	
Property Name EAST ELMONT		Well No. 4	

7. Surface Location

UL - Lot K	Section 33	Township 18S	Range 37E	Feet from 1980	N/S Line FSL	Feet From 1980	E/W Line FWL	County Lea
----------------------	----------------------	------------------------	---------------------	--------------------------	------------------------	--------------------------	------------------------	----------------------

Well Status

TA'D WELL YES	NO	SHUT-IN YES	NO	INJ NO	SWD	OIL	PRODUCER	GAS	DATE 3/20/17
------------------	-----------	----------------	-----------	------------------	-----	-----	----------	-----	------------------------

OBSERVED DATA

	(A)Surface	(B)Internv 1	(C)Internv 2	(D)Prod Csg	(E)Tubing
Pressure	0	—	—	750	7150
Flow Characteristics					
Pull	0/N	Y/N	Y/N	Y/N	CO2 —
Steady Flow	Y/N	Y/N	Y/N	Y/N	WTR —
Surges	Y/N	Y/N	Y/N	Y/N	GAS —
Down to nothing	0/N	Y/N	Y/N	Y/N	Type of Fluid
Gas or Oil	Y/N	Y/N	Y/N	Y/N	Injected for
Water	Y/N	Y/N	Y/N	Y/N	Waterflood if
					applies

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

750 # - CO2 - Failure Shut-in - JMB
Tried To Blow Down oil water mix

Failure

Signature: [Signature]		OIL CONSERVATION DIVISION	
Printed name: PATRICK BENTHE		Entered into RBDMS	
Title: Production Tech		Re-test [Signature]	
E-mail Address: PATRICK.BENTHE@oxy.com			
Date: 3/20/17	Phone:		
Witness: [Signature]			

INSTRUCTIONS ON BACK OF THIS FORM