

HOBBS OCD

MAR 22 2017

RECEIVED

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

BRADENHEAD TEST REPORT

Operator Name <i>OXY</i>	API Number <i>30-D25 05638</i>
Property Name <i>EAST ELMORE</i>	Well No. <i>11</i>

Surface Location

UL Lot <i>M</i>	Section <i>34</i>	Township <i>18S</i>	Range <i>37E</i>	Feet from <i>660</i>	N/S Line <i>FSL</i>	Feet From <i>660</i>	E/W Line <i>FEL</i>	County <i>Lea</i>
--------------------	----------------------	------------------------	---------------------	-------------------------	------------------------	-------------------------	------------------------	----------------------

Well Status

TA'D WELL YES	SHUT-IN NO	INJECTOR NO	SWD	OIL	PRODUCER	GAS	DATE <i>3/20/17</i>
------------------	---------------	----------------	-----	-----	----------	-----	------------------------

OBSERVED DATA

	(A) Surface	(B) Interm (1)	(C) Interm (2)	(D) Prod Csg	(E) Tubing
Pressure	<i>1550</i>				
Flow Characteristics					
Pull	<i>Y/N</i>	<i>Y/N</i>	<i>Y/N</i>	<i>Y/N</i>	CO2 ☐
Steady Flow	<i>Y/N</i>	<i>Y/N</i>	<i>Y/N</i>	<i>Y/N</i>	WTR ☐
Surges	<i>Y/N</i>	<i>Y/N</i>	<i>Y/N</i>	<i>Y/N</i>	GAS ☐
Down to nothing	<i>Y/N</i>	<i>Y/N</i>	<i>Y/N</i>	<i>Y/N</i>	Type of fluid injected for waterflood if applicable
Gas or Oil	<i>Y/N</i>	<i>Y/N</i>	<i>Y/N</i>	<i>Y/N</i>	
Water	<i>Y/N</i>	<i>Y/N</i>	<i>Y/N</i>	<i>Y/N</i>	

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

Signature <i>Patrick Bente</i>	OIL CONSERVATION DIVISION
Printed name: <i>Patrick Bente</i>	Entered into RBDMS
Title: <i>Production Tech</i>	Re-test
E-mail Address: <i>Patrick.Bente@oxy.com</i>	
Date: <i>3/20/17</i>	
Phone: <i>(575) 441-2744</i>	
Witness: <i>[Signature]</i>	

INSTRUCTIONS ON BACK OF THIS FORM