

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

HOBBS OCD

MAR 22 2017

RECEIVED

BRADENHEAD TEST REPORT

Operator Name OX4	APIN 30-025-10996 10986
Property Name G. H. MATTIX Fed.	#5

Surface Location									
UL - Lot E	Section 3	Township 24s	Range 37E	Feet from 1970	N/S Line N	FT 656	E/W Line W	LEA	

Well Status									
TA'D WELL YES	NO	YES	SHUT-IN NO	INJ	INJECTOR NO	SWD	OIL	PRODUCER GAS	3-22-17

OBSERVED DATA

	(A) Surface	(B) Interm(1)	(C) Interm(2)	(D) Prod Casing	(E) Tubing
Pressure	0			0	1150
Flow Characteristics					
Puls	Y/N	Y/N	Y/N	Y/N	
Steady Flow	Y/N	Y/N	Y/N	Y/N	
Surges	Y/N	Y/N	Y/N	Y/N	
Down to nothing	Y/N	Y/N	Y/N	Y/N	
Gas or Oil	Y/N	Y/N	Y/N	Y/N	
Water	Y/N	Y/N	Y/N	Y/N	

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

Signature:	
Printed name: Alejandro Estrella	
Title: Production Tech	
E-mail Address: alex.estrella@ox.com	
Date: 3/22/17	Phone: 575 621 2960
Witness: Gary Robinson	

INSTRUCTIONS ON BACK OF THIS FORM