

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office
BRADENHEAD TEST REPORT

HOBBS CCD

MAR 29 2017

RECEIVED

Operator Name Cross Timber Energy, LLC	API Number 3002523918
Property Name North Vacuum ABO East Unit	Well No. 11

7. Surface Location

U/L - Lot N	Section 18	Township 17S	Range 35E	Feet from 660	N/S Line FSL	Feet From 1902	E/W Line FWL	County Lea
----------------	---------------	-----------------	--------------	------------------	-----------------	-------------------	-----------------	---------------

Well Status

Well Status	SHUT-IN	PRODUCING injection	DATE 3-8-2017
-------------	---------	------------------------	------------------

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

OBSERVED DATA

If bradenhead flowed water, check all of the descriptions that apply:

	(A)Surf-Interm	(B)Interm(1)-Interm(2)	(C)Interm-Prod	(D)Prod Csgng	(E)Tubing
Pressure	0 psi	0 psi		0 psi	0 psi
Flow Characteristics					
Puff	Y / ☒ N	Y / ☒ N	Y / N	Y / ☒ N	
Steady Flow	Y / ☒ N	Y / ☒ N	Y / N	Y / ☒ N	
Surges	Y / ☒ N	Y / ☒ N	Y / N	Y / ☒ N	
Down to nothing	☒ Y / N	☒ Y / N	Y / N	☒ Y / N	
Gas or Oil	Y / ☒ N	Y / ☒ N	Y / N	Y / ☒ N	
Water	Y / ☒ N	Y / ☒ N	Y / N	Y / ☒ N	

If bradenhead flowed water, check all of the descriptions that apply:

CLEAR	FRESH	SALTY	SULFUR	BLACK
-------	-------	-------	--------	-------

Remarks:

INJECTING AT THIS TIME 20 WTR, 0 GAS, 0 CO2

packer / Thg leak
Failure

Signature: Jose Casas	OIL CONSERVATION DIVISION
Printed name: Jose Casas	Entered into RBDMS
Title: lease operator	Re-test
E-mail Address: JCasas@CTFieldsLLC.com	
Date: 3-8-2017	
Phone: 575-746-7220	
Witness:	