

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

HOBBS OCD

APR 12 2017

BRADENHEAD TEST REPORT

RECEIVED

Operator Name DKD		Well No. 30-025-27886
Property Name Richardson FEE SWD		Well No. #2

Surface Location									
UL - Lot K	Section 5	Township 14s	Range 36E	Feet from 1980	N/S Line S	Feet from 1980	E/W Line W	County LEA	

Well Status									
TA'D WELL YES	NO	SHUT-IN YES	NO	INJ INJ	SWD	OIL OIL	GAS GAS	DATE 4-5-17	

OBSERVED DATA

	(A)Surface	(B)Interm(1)	(C)Interm(2)	(D)Prod Csg	(E)Tubing
Pressure	0	—	—	0	20" VAC
Flow Characteristics					
Pull	Y / N	Y / N	Y / N	Y / N	CO2 —
Steady Flow	Y / N	Y / N	Y / N	Y / N	WTR ✓
Surges	Y / N	Y / N	Y / N	Y / N	GAS —
Down to nothing	Y / N	Y / N	Y / N	Y / N	Type of fluid
Gas or Oil	Y / N	Y / N	Y / N	Y / N	Injected if
Water	Y / N	Y / N	Y / N	Y / N	Waterflood if

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

Signature:		OIL CONSERVATION DIVISION
Printed name:		Entered into RBDMS
Title:		Re-test
E-mail Address:		
Date:	Phone:	
Witness: Gary Robinson		

INSTRUCTIONS ON BACK OF THIS FORM