

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

HOBBS

APR 12 2017

RECEIVED

BRADENHEAD TEST REPORT

Operator Name DKP	API Number 30-025-34197
Property Name WATSON 6	Well No. #1

Surface Location

UL - Lot N	Section 6	Township 16s	Range 38E	Feet from 2857	N/S Line S	Feet from 1417	E/W Line W	County LEA
----------------------	---------------------	------------------------	---------------------	--------------------------	----------------------	--------------------------	----------------------	----------------------

Well Status

TA'D WELL YES ☐ NO ☒	SHUT-IN YES ☐ NO ☒	INJECTOR INJ ☐ SWD ☒	PRODUCER OIL ☐ GAS ☐	DATE 4-5-17
--	--	--	---	-----------------------

OBSERVED DATA

	(A)Surface	(B)Interm(1)	(C)Interm(2)	(D)Prod Csg	(E)Tubing
Pressure	0	—	—	0	5"VAL
Flow Characteristics					
Pull	Y ☒ N ☐	Y ☐ N ☒	Y ☐ N ☒	Y ☒ N ☐	CO2 ☐
Steady Flow	Y ☒ N ☐	Y ☐ N ☒	Y ☐ N ☒	Y ☒ N ☐	WTR ☒
Surges	Y ☒ N ☐	Y ☐ N ☒	Y ☐ N ☒	Y ☒ N ☐	GAS ☐
Down to nothing	Y ☒ N ☐	Y ☐ N ☒	Y ☐ N ☒	Y ☒ N ☐	Type of Fluid
Gas or Oil	Y ☒ N ☐	Y ☐ N ☒	Y ☐ N ☒	Y ☒ N ☐	Injected for
Water	Y ☒ N ☐	Y ☐ N ☒	Y ☐ N ☒	Y ☒ N ☐	Water level if applies

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

Signature:	OIL CONSERVATION DIVISION
Printed name:	Entered into RBDMS
Title:	Re-test
E-mail Address:	
Date:	
Phone:	
Witness: Gary Robinson	

INSTRUCTIONS ON BACK OF THIS FORM