

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

APR 06 2017

RECEIVED

BRADENHEAD TEST REPORT

Operator Name CHEVRON USA INC	APL Number 3002524032
Property Name NORTH VACUM ADO WEST UNIT	Well No. 12

7. Surface Location

UL - Lot N	Section 22	Township T15	Range R34E	Feet from 660	N/S Line S	Feet From 1880	E/W Line W	County LEA
----------------------	----------------------	------------------------	----------------------	-------------------------	----------------------	--------------------------	----------------------	----------------------

Well Status

TA'D WELL ☒ YES ☐ NO	SHUT-IN ☒ YES ☐ NO	INJECTOR ☒ INJ ☐ SWD	PRODUCER ☐ OIL ☐ GAS	DATE 3/16/2017
--	--	--	---	--------------------------

OBSERVED DATA

	(A)Surface	(B)Interm(1)	(C)Interm(2)	(D)Prod Csg	(E)Tubing
Pressure	ϕ	—	—	ϕ	ϕ
Flow Characteristics					
Puff	Y / ϕ	Y / N	Y / N	Y / ϕ	CO2 —
Steady Flow	Y / ϕ	Y / N	Y / N	Y / ϕ	WTR —
Surges	Y / ϕ	Y / N	Y / N	Y / ϕ	GAS —
Down to nothing	ϕ / N	Y / N	Y / N	ϕ / N	Type of Fluid
Gas or Oil	Y / ϕ	Y / N	Y / N	Y / ϕ	Injected for
Water	Y / ϕ	Y / N	Y / N	Y / ϕ	Waterflood if applies.

Remarks – Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

Signature: <i>Edme Gatteros</i>	OIL CONSERVATION DIVISION
Printed name: EDME GATTEROS	Entered into RBDMS
Title: SSPS	Re-test
E-mail Address: EDME@CHEVRON.COM	
Date: 3/16/17	
Phone: 575-441-4478	
Witness: <i>[Signature]</i>	

mailed 4.3