

4.12.17

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

BRADENHEAD TEST REPORT

Operator Name Chukon USA INC	API Number 300253603 00000
Property Name Trinity Burgess Abo Unit	Well No. 11

7. Surface Location									
UL - Lot K	Section 22	Township 12	Range 38	Feet from 1650	N/S Line FSL	Feet From 2310	E/W Line FWL	County Lea	

Well Status				
Well Status	SHUT-IN N	PRODUCING INS	DATE 4/4/17	

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

OBSERVED DATA

If bradenhead flowed water, check all of the descriptions that apply:

	(A)Surf-Interm	(B)Interm(1)-Interm(2)	(C)Interm-Prod	(D)Prod Csg	(E)Tubing
Pressure	0	0	N/A	0	420
Flow Characteristics					
Puff	Y/N	Y/N	Y/N	Y/N	
Steady Flow	Y/N	Y/N	Y/N	Y/N	
Surges	Y/N	Y/N	Y/N	Y/N	
Down to nothing	Y/N	Y/N	Y/N	Y/N	
Gas or Oil	Y/N	Y/N	Y/N	Y/N	
Water	Y/N	Y/N	Y/N	Y/N	

If bradenhead flowed water, check all of the descriptions that apply:

CLEAR	FRESH	SALTY	SULFUR	BLACK
-------	-------	-------	--------	-------

Remarks: INJECTING AT THIS TIME ☒ WTR, ☐ GAS, ☐ CO2

Signature: Sergio	OIL CONSERVATION DIVISION
Printed name: Sergio Munoz	Entered into RBDMS
Title: lease OP	Re-test
E-mail Address: SEMUK@chukon.com	
Date: 4/4/17	
Phone: 575-689-5594	
Witness: Kerry Fortner - OCD	

395-3221