

FLARE INSPECTION

Matador
LEASE OR FACILITY NAME Pearson 6 Fed.

WELL # 5 API# 30-025-35845

U.L. N SEC 6 T 18s R 32E

FOOTAGE 990 N/S 2310 E/W (W)

IS A FLARE STACK PRESENT? (YES) NO

IS FLARE ACTIVE? YES (NO)

IS GAS TO FLARE METERED? (YES) NO

AREA AROUND FLARE CLEARED? (YES) NO

ENVIRONMENTAL CONCERNS _____

IS VRU PRESENT? YES (NO)

IS VRU ACTIVE? YES NO

COMMENTS _____

INSPECTOR Gary Robinson DATE 4-20-17