

FLARE INSPECTION

Chevron

LEASE OR FACILITY NAME *Cross Bones 2-29*

Battery → WELL # *1 H* API# 30-*025*-*40706*

U.L. *M* SEC *29* T *18s* R *32e*

FOOTAGE *560* N / *S* *660* E / *W*

IS A FLARE STACK PRESENT? ☒ YES ☐ NO

IS FLARE ACTIVE? YES ☒ NO

IS GAS TO FLARE METERED? ☒ YES ☐ NO

AREA AROUND FLARE CLEARED? ☒ YES ☐ NO

ENVIRONMENTAL CONCERNS _____

IS VRU PRESENT? ☒ YES ☐ NO

IS VRU ACTIVE? ☒ YES ☐ NO

COMMENTS _____

INSPECTOR *Gary Robinson* DATE *4-20-17*