

FLARE INSPECTION

COG
LEASE OR FACILITY NAME Magnum Pronto ST Con
WELL # 5H API# 30- 025 - ~~4013~~ 40163
U.L. 0 SEC 32 T. 19s R. 32E
FOOTAGE 330 N 15 2260 (E) W
IS A FLARE STACK PRESENT? YES NO
IS FLARE ACTIVE? YES NO
IS GAS TO FLARE METERED? YES NO
AREA AROUND FLARE CLEARED? YES NO
ENVIRONMENTAL CONCERNS _____

HOBBS OCD
APR 24 2017
RECEIVED

IS VRU PRESENT? YES NO
IS VRU ACTIVE? YES NO
COMMENTS _____

INSPECTOR Greg Robinson DATE 4-21-17