

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

APR 06 2017

RECEIVED

BRADENHEAD TEST REPORT

Operator Name CHEVRON USA INC	API Number 30-025-23915
Property Name NORTH VACUUM ABO WEST UNIT	Well No. 20

7. Surface Location

UL - Lot L	Section 27	Township 17S	Range 34E	Feet from 1980	N/S Line S	Feet From 660	E/W Line W	County LEA
----------------------	----------------------	------------------------	---------------------	--------------------------	----------------------	-------------------------	----------------------	----------------------

Well Status

Well Status NO	SHUT-IN NO	PRODUCING YES	DATE 3-18-17
--------------------------	----------------------	-------------------------	------------------------

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

OBSERVED DATA

If bradenhead flowed water, check all of the descriptions that apply:


	(A)Surf-Interm	(B)Interm(1)-Interm(2)	(C)Interm-Prod	(D)Prod Casing	(E)Tubing
Pressure	0	N/A	N/A	30	400
Flow Characteristics					
Puff	Y / N	Y / N	Y / N	Y / N	
Steady Flow	Y / N	Y / N	Y / N	Y / N	
Surges	Y / N	Y / N	Y / N	Y / N	
Down to nothing	Y / N	Y / N	Y / N	Y / N	
Gas or Oil	Y / N	Y / N	Y / N	Y / N	
Water	Y / N	Y / N	Y / N	Y / N	

If bradenhead flowed water, check all of the descriptions that apply:

CLEAR	FRESH	SALTY	SULFUR	BLACK
-------	-------	-------	--------	-------

Remarks:

INJECTING AT THIS TIME ___ WTR, ___ GAS, ___ CO2

Signature: 	OIL CONSERVATION DIVISION
Printed name: AUSTIN PASQUE	Entered into RBDMS
Title: FSA	Re-test
E-mail Address: ctym@chevron.com	
Date: 3-18-17	
mailed 4:3	
Phone: 575-513-0363	
Witness:	